

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

CS474
NNE
1/2-1
0.742 mi.
3918 ft.

POLE #37946, 86A181027 TRANSFORMER
2445 WEST 2ND ST
BROOKLYN, NY

NY Spills S118706944
N/A

Site 1 of 2 in cluster CS

Relative:
Higher

Actual:
12 ft.

SPILLS:

Name: POLE #37946, 86A181027 TRANSFORMER
Address: 2445 WEST 2ND ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1604123 / 2016-08-11
Facility ID: 1604123
Facility Type: ER
DER Facility ID: 484693
Site ID: 530618
DEC Region: 2
Spill Cause: Storm
Spill Class: C4
SWIS: 2401
Spill Date: 2016-07-26
Investigator: RWAUSTIN
Referred To: Not reported
Reported to Dept: 2016-07-26
CID: Not reported
Water Affected: Not reported
Spill Source: Transformer
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2016-07-26
Spill Record Last Update: 2016-08-11
Spiller Name: RICHARD SLOTE
Spiller Company: CON ED
Spiller Address: 2445 WEST 2ND ST
Spiller Company: 999
Contact Name: RICHARD SLOTE
DEC Memo: "emis 248941 8/11/16 - Austin - 10 oz puddle of dielectric fluid (non-PCB) discovered on pavement underneath Con Ed pole transformer - Con Ed contained and cleaned up the spill - See document files for further information - Spill closed - end"
Remarks: "12 ounces to concrete. unable to cleanup within 2 hour time. lightning strike"

All Materials:

Site ID: 530618
Operable Unit ID: 1279411
Operable Unit: 01
Material ID: 2284459
Material Code: 0541A
Material Name: dielectric fluid
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported